NVL Laboratories, Inc.

4708 Aurora Ave. N., Seattle, WA 98103 Tel: 206.547.0100, Fax: 206.634.1936 www.nvllabs.com

Analysis Report

AIHA - IH # 101861 WA - DOE # C1765



Total Metals

Client: NVL Field Services Division Address: 4708 Aurora Ave. N. Seattle, WA 98103

Batch #: 1409906.00 Matrix: Bulk

Method: EPA 6010 / 7471 (Hg) Client Project #: 2012-494

> Date Received: 6/13/2014 Samples Received: 1 Samples Analyzed: 1

Attention: Mr. Munaf Khan Project Location: 3317 3rd Ave South, Seattle, WA 98134

Lab ID	Client Sample #	Elements	Sample wt (g)	RL mg / kg	Results in mg / kg	Results in ppm
14061273	61114-MG-B-1	Silver (Ag)	0.2362	17.0	< 17.0	< 17.0
		Arsenic (As)	0.2362	17.0	< 17.0	< 17.0
		Cadmium (Cd)	0.2362	17.0	< 17.0	< 17.0
		Chromium (Cr)	0.2362	17.0	27.0	27.0
		Mercury (Hg)	0.2362	0.9	< 0.8	< 0.8
		Lead (Pb)	0.2362	17.0	< 17.0	< 17.0
		Copper (Cu)	0.2362	17.0	2500.0	2500.0
		Nickel (Ni)	0.2362	17.0	26.0	26.0
		Zinc (Zn)	0.2362	17.0	55.0	55.0

Sampled by: Client

Analyzed by: Fatima Khan Reviewed by: Nick Ly

Date Analyzed: 06/16/2014 Date Issued: 06/16/2014

for Nick Ly, Technical Director

mg/ kg = Milligrams per kilogram

ppm = Parts per million

RL = Reporting Limit '<' = Below the reporting Limit

Note: Method QC results are acceptable unless stated otherwise.

Unless otherwise indicated, the condition of all samples was acceptable at time of receipt. Bench Run No: 34-0616-6

Page 1 of 1

NVL Laboratories, Inc.

4708 Aurora Ave N, Seattle, WA 98103
Tel: 206.547.0100 Emerg. Cell: 206.914.4646
1 888 NVI I ABS (685 5227) www.nvllabs.com

CHAIN of CUSTODY SAMPLE LOG



1.888.NV	L.LABS (685.5221) www.nviiabs.com	1						
	Client NVL Lab	oratories Inc			h Number				
	Street 4708 Aut	ora Ave N		Client Jo	Client Job Number 2012-494				
	Seattle, \	NA 98103		Tota	I Samples				
Project M	anager Munaf Kl	nan		Turn Arc	ound Time 1-Hr 8-Hr		☐ 5 ☐ 6.40		
roiect Lo	ocation 3317 3rd	Avenue South			☐ 2-Hrs ☐ 12-h ☐ 4-Hrs 尾 24-h		<u> </u>		
,	Seattle, \	NA 98134				or TAT less than	24 Hrs		
				Ema	il address				
	Phone: (206) 44	7-0263 Fax :	(206) 447		-				
☐ Asbe	estos Air 🔲 PC	M (NIOSH 7400)	TEM (NIOSH 7402) 🗌 TEM (A	AHERA) 🗌 TEM (EPA Le	vel II) 🔲 Oth	er		
☐ Asbe	estos Bulk 🗌 PLN	/I (EPA/600/R-93/1	16) 🗌 F	PLM (EPA Point Count)	PLM (EPA Gravimetry)	☐ TEM BUL	K		
☐ Mold	I/Fungus	d Air 🔲 Mold Bull	k 📗 R	otometer Calibration					
METAL: Total TCLF Cr 6	Metals ☐ FAA	A (ppm)		☐ Soil Paint Chips in %		mium (C (Pb) ury (Hg)	er Metals All 3 opper (Cu) ckel (Ni) nc (Zn)		
			nce Dust	Other (Specify)		X SIL	LUBER (Ag)		
	nalysis Silic		able Dust	\ 🗔	/ 10 A				
Conditio	on of Package:	Good ∐Damag	ged (no sp	illage)	ge (spillage)				
Seq.#	Lab ID	Client Sample	Number	Comments			A/R		
1		61114-MG-	8-1	BLASTING ME	0 A				
2									
3									
4									
5									
6									
7									
8									
9									
10									
11									
12									
13									
14									
15									
	Drint	Below	Sian Belg		Company	Date .	Time		
		rus Guspan	Sidil bei		NVL LABS	6/11/14	14:00		
	quished by	± .		7	4	6/12/14	13:15		
	Received by	NUTA TELAN	Buch	islativas	Dal	12/13/14	1315		
	Analyzed by	Thing than	070	All ()	Meeroly	6/16/14	11.200		
	ts Called by	Still of book	, I	Home	, and any	- Officer c	.(20 =		
	ts Faxed by								
Specia	I Instructions: (Jnless requested in	n writing, a	all samples will be dispose	ed of two (2) weeks after and	alysis.			
Results	s report to								